

APPROXIMATE EXTENT OF SOLID WASTE MANAGEMENT UNIT (SWMU)

EXISTING MONITORING WELL LOCATION

SURVEYED GEOPROBE LOCATION INSTALLED IN 2004

GEOPROBE LOCATION - REFUSAL ENCOUNTERED

BOLD VALUE INDICATES RESULT EXCEEDS RESIDENTIAL RBC BOLD AND SHADED VALUE INDICATES RESULT EXCEEDS RESIDENTIAL & INDUSTRIAL RBC

BOXED VALUE INDICATES RESULT EXCEEDS ECO-SCREENING

INDICATES RESULT EXCEEDS RESIDENTIAL, INDUSTRIAL RBC & ECO-SCREENING CRITERIA

PHASE I TEST PIT LOCATION

OBJECT ENCOUNTERED IN PHASE 1 TEST PIT

 ${\sf J}={\sf THE}$ REPORTED CONCENTRATION FOR THIS ANALYTE IS AN ESTIMATED CONCENTRATION.

 $\mathsf{U} = \mathsf{THE}$ REPORTED CONCENTRATION FOR THIS ANALYTE WAS NOT DETECTED ABOVE LABORATORY DETECTION LIMITS.

Prepared/Date: MS 11/2005 Checked/Date: DJN 11/2005

SOURCE:

COMPILED BY PRO MAPS OF MORRISTOWN, NJ FROM AERIAL PHOTOGRAPHY FLOWN BY KEYSTONE AERIAL PHOTOGRAPHS OF PHILADELPHIA, PA. FLOWN AT 1"=400' USING DATUM OF NAD 83 SOUTH ZONE — PA AND NAVD 88. SURVEY SUPPORT BY JAMES M. STEWART OF PHILADELPHIA, PA.



DELAWARE VALLEY Honeywell Route 13 (Delaware County) Claymont, DE

WORKS FACILITY



SWMU 15 TEST PIT LOCATIONS AND CROSS SECTIONS WITH ORGANIC COMPOUND ANALYTICAL EXCEEDANCES

Project 3485-05-0043

Figure 8